

Instructions of Coolmay Software Installation

I. PLC software: GX Works2

1. PC system: Win 7/ Win 10
2. Installation video

<https://www.youtube.com/watch?v=eNZ3Q1uhWc8&t=30s>

3. Download link

<https://en.coolmay.com/Download.aspx?ColumnId=152&Language=36&Terminal=41>

4. Icon



5. FAQ

- a) Mini type-B USB port can't be recognized, and the program can't be downloaded.

Solutions: Install USB programming port drive

<https://en.coolmay.com/Download.aspx?ColumnId=208&Language=36&Terminal=41>



Coolmay 3G PLC, all-in-one USB programming port drive installation steps in WIN7&WIN10

II. HMI software: “CoolmayHMI”

1. PC system: Win 7/ Win 10
2. Installation video

<https://www.youtube.com/watch?v=rSPMx4v3x7c&t=54s>

3. Download link

<https://en.coolmay.com/Download.aspx?ColumnId=159&Language=36&Terminal=41>

4. Icon



5. FAQ

a) Failure to install the software

Solutions: Turn off “Firewall” and all anti-virus software in your PC and then install the software.

b) When install the software, the program can't be downloaded successfully.

Solutions: The driver is not recognized by your PC. Please install the HMI driver by hand according to the instruction here:

<https://en.coolmay.com/Download.aspx?ColumnId=157&Language=36&Terminal=41>



HMI Driver Installation Steps in Win10.pdf

Or refer to this video:

<https://youtu.be/1r68wwg5h0o>

III. HMI software: “mView”

1. PC system: WIN XP/ WIN7/ WIN10
2. Installation video

<https://youtu.be/d5bMUWJ2zeg>

3. Download link

<https://en.coolmay.com/Download.aspx?ColumnId=159&Language=36&Terminal=41>

4. Icon

